

Job Description

Powder Coat Line Operator/Painter

Department:	Powder Coat
Reports To:	Powder Coat Supervisor
FLSA Classification:	<i>Non-Exempt</i>

JOB SUMMARY:

Powder Coat Line Operators are responsible from load, unloading, masking and unmasking part on the conveyor line. Painters are expected to set up and operate manual and auto paint equipment used for painting various components on a moving conveyor line.

ESSENTIAL DUTIES:

- Load and unload parts to the conveyor line
- Mask and unmask parts according to the process sheet
- Spray off debris from the parts on the line as they come through
- Inspect parts for defects
- Load parts on pallets for shipping.
- Maintain a safe and clean working environment by complying with company procedures and regulations
- Applying a wide range of powder coatings per manufacturers requirements on a multiple variety of castings and stampings
- Ensure all work produced in the environmentally controlled paint room meets customers quality expectations
- Provide input for new ideas to improve line density of products while maintaining top quality to customers

MINIMUM QUALIFICATIONS:

- Must have a high school diploma or GED
- Must have previous manufacturing experience
- Must be able to lift up to 50 lbs. on a regular basis
- Must be able to use a computer
- Must have reliable transportation

PREFERRED QUALIFICATIONS:

- Must be able to work from and read detail drawings and specifications.
- Must be able to work in fast paced environment
- Must work well in team environment
- Must be organized, detail oriented and dependable